

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 20 August 2019
Australia – Victoria

No. 198(T) - 2019

Local Port of Port Phillip

St Kilda
Isolated Danger buoy – Light Non-Operational

Date: **Immediate**

Details: Mariners are advised that the light with characteristics Fl(2) W10s for the Isolated Danger buoy situated south west of St Kilda Harbour at approximate location 37°52.197'S, 144°57.539'E (WGS84), is non-operational.

The light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution when in the vicinity of the buoy.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Hayden Regan
A/Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.