

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 27 August 2020
Australia – Victoria

No. 234(T)– 2020

Local Port of Port Phillip

Indented Head
Governor Reef Channel - Port lateral buoy Light Non-operational.

Date: **Immediate**

Details: Mariners are advised that the Governor Reef Channel Port Lateral Buoy Light with characteristics Fl.R.3s at approximate location 38°08.930'S, 144°43.336'E (WGS84) is currently non-operational.

The light will be re-instated as soon as practicable.

Mariners are advised to exercise caution when navigating within the vicinity of Governor Reef.

Charts & Publications

Affected: AUS 143, 157.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.