

# NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No.212 OF 2021**

**PORT OF CORNER INLET AND PORT ALBERT**

**CORNER INLET – TOORA CHANNEL**

**BEACON LIGHTS AND DAY SHAPE EXCHANGE COMPLETED**

**CHANGE TO CHANNEL LIGHT CHARACTER AND CONFIGURATION.**

**DATE:** 5<sup>th</sup> July 2021

**DETAILS:** Mariners are advised that following the recent storm event in Corner Inlet and Port Albert the Corner Inlet Toora Channel beacon lights and day shape exchange has been completed. There is no change to the positions of the Toora Channel Beacons Numbered 1 to 8. Toora Channel No.9 Light Buoy remains unchanged. The changes to the light character of each beacon follows;  
Toora No.1 Fl.G.4s 4M  
Toora No.2 Fl.R.4s 4M  
Toora No.3 Fl.G.4s 4M  
Toora No.4 Fl.R.4s 4M  
Toora No.5 Fl.G.4s 4M  
Toora No.6 Fl.R.4s 4M  
Toora No.7 Fl.G.4s 4M  
Toora No.8 Fl.R.4s 4M  
Toora Channel lights Numbered 1 to 8 are synchronized with the flash rate of 1s ON 3s OFF.

**CHARTS** Chart Aus.181 & ENC AU439146  
**AFFECTED:**

**PUBLICATIONS** Admiralty Sailing Directions – Australian Pilot Vol II NP14  
**AFFECTED:** Gippsland Ports Waterways online website available at;  
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER** No further notice will be issued.  
**NOTICE:**

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**