

# NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No.222 OF 2021**

**PORT OF CORNER INLET AND PORT ALBERT**

**CORNER INLET – MAIN CHANNEL**

**CHANGE TO LIGHT BUOY FLASH CHARACTERS**

**LIGHTS SYNCHRONIZED.**

**DATE:** 13<sup>th</sup> July 2021

**DETAILS:** Mariners are advised that the light Flash Character of Corner Inlet Main Channel Light Buoys #2, #4 and #6 have been changed as follows;

Corner Inlet No.2 Port Lateral Mark Buoy Fl.R.4s. 3m 4M

Corner Inlet No.4 Port Lateral Mark Buoy Fl.R.4s. 3m 4M

Corner Inlet No.6 Port Lateral Mark Buoy Fl.R.4s. 3m 4M

There has been no change to the position of the Main Channel Light Buoys.

The Corner Inlet Main Channel lights numbered 2, 4 and 6 have been synchronized with the flash rate of 0.5s ON 3.5s OFF.

**CHARTS  
AFFECTED:** Chart Aus.181 & ENC AU439146

**PUBLICATIONS  
AFFECTED:** Admiralty Sailing Directions – Australian Pilot Vol II NP14  
Gippsland Ports Waterways online website available at;  
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER  
NOTICE:** No further notice will be issued.

**CAPT. BEVIS HAYWARD  
HARBOUR MASTER**