NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No. 228(T) OF 2022

PORT OF MALLACOOTA INLET - BASTION POINT BOAT RAMP

NAVIGATION WARNING

APPROACH CHANNEL – ROCKS DISLODGED FROM SEA WALL DEPTHS COMPROMISED WITH RESTRICTED APPROACH ACCESS

DATE: 21st June 2022

PREVIOUS
NOTICE:Notice to Mariners No.213 of 2020 is referred and cancelled.
Notice to Mariners No 007 of 2021 – Bar Crossing Warning – is
referred.

DETAILS: The recent severe weather event causing strong South Westerly wind conditions with damaging seas and swells have dislodged 3 large rocks from the structure of the Bastion Point Breakwater wall at the entrance to the Ocean Access Boat Ramp.

East Gippsland Shire has reported that the rocks are located near the Breakwater wall midway between the Boat Ramp Port Hand Lateral Beacons #2 & #4. The approximate position of the rocks is; Lat. 37° 34.250' S Lon. 149° 45.896' E Datum WGS84

The rocks are compromising the available depth and restricting the approach in that position. The rocks are located in a surf zone and are unable to be marked. East Gippsland Shire will remove the rocks as soon as is practically possible.

Mariners are advised to take extra precaution and avoid entering or departing the boat ramp approach entrance close to the Breakwater wall.

A photograph and map indicating the position of the rocks is attached to this Notice

Mariners are advised that transits of the approach channel and entrance should only be carried out during fine weather conditions

NOTICE TO MARINERS

GIPPSLAND PORTS



and if there is sufficient height of tide taking into consideration the vessels draft, the existing sea state, predicted weather conditions for the duration of the voyage and <u>the expected conditions and tide height for the time of return.</u>

Passage through the approach channel should only be attempted by experienced vessel operators who possess sound knowledge of the conditions to be expected during the transit of the channel taking into consideration the position of the dislodged rocks and the prevailing weather and sea state at the time.

Passengers and crew should be briefed so they are aware of the heightened risk that may prevail at the time of departure or arrival

WEAR A LIFE JACKET

Vessel Operators are reminded that this is an Ocean Access Boat Ramp and large swells may occur, even at times when the conditions are assessed as being good.

Night navigation is considered extremely dangerous and should not be attempted.

IF IN DOUBT DON'T GO OUT

Further details can be obtained from Gippsland Ports Harbour Master on 0427 610 025

CHART Chart Aus. 805 – ENC AU438149 AFFECTED:

 PUBLICATIONS
 Gippsland Ports Waterways Online available at

 AFFECTED:
 https://www.gippslandports.vic.gov.au/boating/waterways-online/

FURTHER A further notice shall be issued **Notice:**

CAPT. BEVIS HAYWARD HARBOUR MASTER



