

The following Notice to Mariners is published for general information

Australia – Victoria

No. 412 (T) - 2022

PORT OF MELBOURNE PORT PHILLIP BAY EAST CARDINAL MARK BUOY ADRIFT

Date: 21 November 2022

Refers: N/A

Details: Mariners are advised that the East Cardinal Mark Buoy Q (3) 10s established in the below position is unlit and approximately 250m west from its established position in Port Phillip Bay.

<i>Approximate Location</i>	<i>Established Position</i>		<i>Characteristics</i>
	<i>Latitude</i>	<i>Longitude</i>	
250m west of established position	38° 13.909' S	144° 50.614' E	Q (3) 10s

Mariners are advised to navigate with caution in the vicinity of the drifting buoy.

For further information, please contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Charts & Publications affected

AUS 143


Further notice:

Further notice will be issued.



**Warwick Laing
Harbour Master**

East Cardinal Mark Buoy



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website www.vicports.vic.gov.au