

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Australia - Victoria

No. 014 (T) - 2023

## PORT OF MELBOURNE PORT PHILLIP BAY TEMPORARY WAVE MONITORING BUOYS ESTABLISHED IN PORT MELBOURNE WATERS AND LOCAL PORT OF PORT PHILLIP WATERS - AMENDED

Date: 11 January 2023

Refers: NtM 436 (T) / 2022 and is hereby cancelled.

**Details:** Mariners are advised that a wave monitoring buoy originally established in the

following position 38° 03.804′ S 144° 52.002′ E has been recovered.

The following table of buoys established in the following positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or about

November 2023.

Approximate Location	Latitude	Longitude	Characteristics
<u>Port Melbourne</u> <u>Waters</u>			
Werribee	37° 59.100′ S	144º 46.512' E	FL (Y) 2.5s
<u>Local Port of Port</u> <u>Phillip</u>			
Sandringham	37° 58.719′ S	144° 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	FL (Y) 2.5s

For further information, contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Mariners are advised to navigate with caution in the vicinity of the buoys.

Charts & AUS 143, 155, 157

Publications ENC AU5RIP01, AU5MEL01

affected

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.

Further notice:

Further notice will be issued.

David Tilsley
Deputy Harbour Master
(Navigation Services)



WAVE MONITORING BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.