

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 14 February 2023
Australia – Victoria

No. 082(T) - 2023

Local Port of Port Phillip

Williamstown

Williamstown Mooring Field – Isolated Danger Buoy Light Non-Operational

Date: Immediate

Details: Mariners are advised that the Isolated Danger Buoy light, with characteristics Fl(2)10s, situated in the eastern portion of the Williamstown Mooring Field at approximate location 37°51.413'S, 144°54.229'E (WGS84) is non-operational.

The light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the buoy.

Charts & Publications

Affected: AUS 143, 154, 155

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Peter Kemp

A/Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.