

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

## Australia – Victoria No. 346 (T) - 2023 PORT OF MELBOURNE PORT MELBOURNE CHANNEL-SOUTH BEACON 8 OFF STATION

Date:	20 August 2023
-------	----------------

Refers: NtM 345 (T) – 23 and is hereby cancelled.

Details: Mariners are advised that Port Melbourne Channel-South Beacon 8 located in position 37° 53.856' S 144° 55.577' E is off station.

The beacon is lying on the seafloor immediately to the northeast of its charted position. The beacon presents an obstruction as follows:

- Beacon 8 charted position: least depth of 8.6m
- Beacon 8 extremity to the northeast: least depth of 13.4m

A virtual aid to navigation **TB12** is established at the northeast extremity of the beacon in the following position: **37° 53.850' S 144° 55.588' E** 

A port hand lateral mark buoy has been deployed directly to the north of the fallen beacon position, details as follows:

Buoy	Characteristic	Approximate Position
Port hand lateral mark	FI(2)R.4S	37° 53.829' S 144° 55.587' E
(without top mark)		

For further information, please contact Melbourne VTS on VHF Channel 12 or call 9644 9700.

## Mariners are advised to navigate with additional caution in the vicinity of Port Melbourne Channel-South Beacon 8 and TB12.

Charts & AUS 155 Publications ENC AU5MEL01 affected:


> This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.

Further notice: Further notice will be issued.


-

David Tilsley Deputy Harbour Master (Navigation Services)

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



## **TEMPORARY BUOY**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.