

The following Notice to Mariners is published for general information

Australia – Victoria

No. 360 (T) - 2023

**PORT OF MELBOURNE
WEBB DIRECTIONAL LIGHT UNRELIABLE**

Date: 6 September 2023

Refers: N/A

Details: Mariners are advised that Webb directional light, located in position **37° 50.842' S 144° 54.322' E**, is **unreliable**.

For more information, contact Melbourne VTS on (03) 9644 9700 or on VHF Channel 12.


Mariners are advised to navigate with additional caution in the vicinity of Webb directional light.

Charts & Publications affected: AUS 155
ENC AU5MEL01

Further notice: Further notice will be issued.



David Tilsley
Deputy Harbour Master
(Navigation Services)



NOT FOR NAVIGATIONAL USE

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
 The requirements of section 232(2) have been taken into account.