

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 12 July 2019**  
**Australia – Victoria**

**No. 171(T) – 2019**

**Local Port of Port Phillip**

**Indented Head**  
**Governor Reef Channel – Lit Port Lateral Buoy - Missing.**

**Date:** **Immediate**

**Details:** Mariners are advised that the Port Lateral Can shaped Buoy at approximate location, 38°09.231'S, 144°43.491'E (WGS84) and lit with characteristics Fl.R.3s is missing.

The buoy will be reinstated as soon as practicable.

**Mariners are advised to exercise caution when navigating within the vicinity of Governor Reef.**

**Charts & Publications**

**Affected:** AUS 143 &157.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Victor Teoh  
Senior Manager Local Ports and Waterways  
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).