



WesternPort

VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

STONY POINT, 1st August 2005

AUSTRALIA – VICTORIA N0: 68/05

PORT OF HASTING

Maritime Transport Security Regulations 2003 Restricted Zones

Date: Effective 1st August 200

Details: Mariners are advised that:

The following piles with light characteristics Fl (Y) 4s, 5m, (*Fl 0.5s, Eclipse 3.5s*) have been put in place around Crib Point and Long Island Point Oil Terminal Jetties. The lights are synchronized. They mark the 100m Maritime Security Zones around the Oil Terminals.

The following Warning Notice is displayed on the piles.

WARNING

**THIS AREA IS A
PORT SECURITY
ZONE
ACCESS TO THE ZONE
IS CONTROLLED AND
UNAUTHORISED ENTRY
IS AN OFFENCE UNDER
THE MARITIME SECURITY
REGULATIONS 2003**

PORT SECURITY OFFICER



Westernport

The positions of the piles are as follows;

Crib Point

WGS84	LATITUDE	LONGITUDE
CP2	38 20.803	145 13.500
CP3	38 21.004	145 13.320
CP4	38 21.215	145 13.531

Long Island Point

WGS84	LATITUDE	LONGITUDE
LIP1	38 18.319	145 13.608
LIP2	38 18.260	145 13.671
LIP3	38 18.446	145 13.558
LIP4	38 18.592	145 13.690

Charts affected: AUS151 AUS 152 AUS156

A further notice will be issued.

**DICK COX
HARBOUR MASTER
PORT OF HASTINGS**