

# NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No.017 OF 2020**

**PORT OF CORNER INLET AND PORT ALBERT**

**LEWIS CHANNEL AIDS TO NAVIGATION**

**BEACON EXCHANGE PROGRAM COMPLETED**

**DATE:** 16<sup>th</sup> January 2020

**PREVIOUS NOTICE:** NtoM No. 156(T) of 2019 is referred and cancelled.  
NtoM No. 232(T) of 2019 is referred and canceled

**DETAILS:** Mariners are advised that the beacon exchange program commenced in October 2019 has been completed. There is no change to the position or the light characteristic of the beacons.

The beacons exchanged in Lewis Channel are;  
**Beacon No.2**, Port hand lateral beacon (Fl.R 2s)  
**Beacon No.3** Starboard hand lateral beacon (Fl.G 4s)  
**Beacon No.9** Starboard hand lateral beacon (Fl.G 4s)

Further information can be obtained by calling the Gippsland Ports Harbour Master on 0427 610 025

**CHARTS AFFECTED** .Chart Aus. 181 & Aus. 182

**PUBLICATIONS AFFECTED:** Admiralty Sailing Directions – Australian Pilot Vol II NP14  
Gippsland Ports Waterways online website available at;  
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**