

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 21 February 2020**  
**Australia – Victoria**

**No. 068(T) - 2020**

**Local Port of Port Phillip**

**Williamstown**  
**Williamstown Mooring Field – Lit Isolated Danger Buoy Missing**

**Date:** **Immediate**

**Details:** Mariners are advised that the isolated danger buoy lit with characteristics Fl(2)W10s, in the eastern portion of the Williamstown Mooring Field at approximate location 37°51.413'S, 144°54.229'E (WGS84) is missing.

The buoy marks a submerged navigational hazard and will be re-instated as soon as practicable.

**Mariners are advised to navigate with caution within the vicinity of the missing buoy.**

**Charts & Publications**

**Affected:** AUS 143, 154, 155

**Further Notice:** A further Notice will be issued.

**If you require any further information please contact Parks Victoria on 13 1963.**

Deven Sumpth

A/ Senior Manager Local Port & Waterways  
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).