

Australia – Victoria

No. 242 – 2020

PORT OF MELBOURNE

WEBB DOCK 4 EAST AND 5 EAST REVISED BERTH INFORMATION

Date: 02 September 2020

Refers: NA

Details: Mariners are advised that due to the completion of berth upgrade works at Webb Dock 4 East and 5 East as such Harbour Masters Directions 11th Edition May 2019, Table 3(j) Berth information, berthing and unberthing in is amended as follows;

Table 3(j) Berth information, berthing and unberthing

Berth		Maintained depth (m)	Ship's limits at berth (m)		Wharf height (m) above Chart Datum	General remarks
Name	Length (m)	Berth	Max. draught	Max. length		
Webb Dock 4 East	660	14.6	14.0	347 ⁷	3.05	Container terminal berths Preferred, head out berthing only Maximum displacement: *118,000 t ⁷ Contact VPCM for LOA>310 m *vessels with displacement greater than 118,000 t but less than or equal to 140,000 t can berth subject to the use of a Docking Aid approved by the HM
Webb Dock 5 East						

As a result of the upgrades to Webb Dock 4 East and 5 East, vessels with a displacement greater than 118,000 t but less than or equal to 140,000 t can berth with a berthing speed of 0.11m/s and the use of a Docking Aid (PPU) approved by the Harbour Master.

Pilots will be required to ensure that their (PPU) units are approved by the Harbour Master and that the berthing speed does not exceed 0.11m/s

For more information contact Melbourne Vessel Traffic Services on VHF Channel 12 or 9644 9700.

Charts & Publications affected:

Harbour Masters Directions 11th Edition May 2019 Section 3.15 Table 3(j).

Further notice: No further notice will be issued.



Kell Dillon
Harbour Master