

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.180 OF 2021

PORT OF CORNER INLET AND PORT ALBERT

CORNER INLET ENTRANCE CHANNEL

No1 SOUTH CARDINAL MARK BUOY BACK ON STATION

DATE: 14th June 2021

PREVIOUS NOTICE: Notice to Mariners No.174(T) of 2021 is referred and cancelled.

DETAILS: Mariners are advised that the Corner Inlet Entrance Channel No.1 South Cardinal Mark Buoy (VQ(6)+LFI.10s) has been reinstated back on station in Position;
Lat. 38° 51.238' S
Lon. 146° 35.692' E Datum WGS84

CHARTS AFFECTED: Chart Aus.181 & ENC AU439146

PUBLICATIONS AFFECTED: Admiralty Sailing Directions – Australian Pilot Vol II NP14
Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**