

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 07 April 2022

Australia – Victoria

No. 128(T) - 2022

Local Port of Port Phillip

Beaumaris

Ricketts Point South Cardinal Mark Pile Lights Partially Obscured

Date: Immediate

Details: Mariners are advised that the navigation lights on two South Cardinal Mark Piles, marking the southern boundary of Ricketts Point Marine Sanctuary detailed in the table below, are partially obscured and are not visible from all directions.

| Description | Locations | Characteristics |
|---------------------|---------------------------|------------------|
| South Cardinal Mark | 37° 59'57"S, 145° 02'03"E | Q (6) + LFl.15s |
| South Cardinal Mark | 37° 59'52"S, 145° 02'18"E | VQ (6) + LFl.10s |

The issue will be resolved as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the piles.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further notice will be issued

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.