

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia - Victoria

No. – 139 (T) - 2022


PORT OF MELBOURNE PORT PHILLIP BAY - INSTALLATION WORKS

Date:	13 April 2022	
Refers:	NA	
Details:	Mariners are advised that the Vessel " Tek Ocean Spirit " is scheduled to conduct installation works in vicinity of Nepean Bay from 15 April – 16 April 2022.	
	Vessel will complete the installation of 16 Pyramid artificial reef units off Point Nepean, assisted by work boat <i>Capability Study.</i>	
	Mariners are advised to remain 250m clear of Tek Ocean Spirit, navigate with caution when in vicinity and shall reduce speed having due regard to the safety of the operation.	
	The site engineer can be contacted on 0437 584 992.	
	For further information contact Melbourne VTS on 9644 9700.	
Charts & Publications affected	AUS 143, AUS 144, AU5RIP01	
Further notice:	Further Notice will be issued	

D. 1. Sheanan

David Shennan Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.

Reef Coordinates:

Unit	Latitude	Longitude
1	38 17.94690 S	144° 40.65402 E
2	38 17.95332 S	144° 40.65378 E
3	38° 17.95350 S	144° 40.66200 E
4	38° 17.94702 S	144° 40.66224 E
5	38° 17.96166 S	144° 40.62438 E
6	38° 17.96814 S	144° 40.62414 E
7	38 17.96832 S	144° 40.63242 E
8	38 17.96184 S	144° 40.63260 E
9	38 17.93562 S	144° 40.61088 E
10	38 17.94210 S	144° 40.61064 E
11	38 17.94228 S	144° 40.61892 E
12	38 17.93580 S	144° 40.61910 E
13	38 17.92146 S	144° 40.64304 E
14	38 17.92794 S	144° 40.64286 E
15	38 17.92812 S	144° 40.65108 E
16	38 17.92164 S	144° 40.65126 E

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.