

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia – Victoria No. – 182 (T) - 2022 PORT MELBOURNE YARRA RIVER INSPECTION AND STRENGTHENING WORKS FOR SERVICES PROTECTION BETWEEN YARRA RIVER BEACONS 33/34 AND 35/36- EXTENDED

| Date: | 18 May 2022 |
|-----------------------------------|--|
| Refers: | NtM 161 (T) / 2022 and is hereby cancelled. |
| Details: | Mariners are advised that inspection and strengthening works for the services protection between Yarra River beacons 33/34 and 35/36 is now extended until approximately 15 June 2022. |
| | Works will be conducted around shipping and from the following boats: |
| | MV Pro Diver (Primary Dive Vessels) and MV Norgate |
| | Vessels operating within the vicinity of the works area shall reduce vessel speed so as to create no wash and pass the support vessel at a safe distance. The on water works supervisor in operational control of the works is contactable on 0409 666 272 or alternatively on 0417 100 624 or VHF Ch.12. |
| | For more details, please contact Melbourne VTS on (03) 9644 9700 or on VHF Channel 12. |
| | Mariners are advised to navigate with additional caution and reduce speed so as to create no vessel wash when in the vicinity of the works at the services protection. |
| Charts & Publications affected | (ENC) AU5MEL01 |
| Further notice: | Further Notice will be issued |

Warwick Laing Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.





Figure 2. Work Zone - East of River Centreline (note Beacons 33 and 34 are south of image)

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.