

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 6 June 2022**  
**Australia – Victoria**

**No. 212(T) – 2022**

**Local Port of Port Phillip**

**Indented Head**  
**Governor Reef Channel – Lit Port Lateral Buoy Missing**

**Date:** **Immediate**

**Details:** Mariners are advised of a missing lit Port Lateral Buoy marking Governor Reef Channel, lit with characteristics Fl.R.3s at approximate location (WGS84): 38°08.933'S, 144°43.339'E.

The buoy will be reinstated as soon as practicable.

**Mariners are advised to navigate with caution within the vicinity of Governor Reef.**

**Charts & Publications**

**Affected:** AUS 143 &157.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

David Ritman

Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).