

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 27 June 2022 Australia – Victoria

No. 231 - 2022

Local Port of Port Phillip

Indented Head

Governor Reef Channel - Lit Port Lateral Buoy Reinstated

Date: Immediate

Previous Notice: 212(T)-22 is referred and cancelled

Details: Mariners are advised of a missing lit Port Lateral Buoy marking Governor Reef

Channel, lit with characteristics Fl.R.3s at approximate location (WGS84):

38°08.933'S, 144°43.339'E, has been reinstated.

Mariners are advised to navigate with caution within the vicinity of Governor

Reef.

Charts & Publications

Affected: AUS 143 &157.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

