

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 21 September 2022
Australia – Victoria

No. 321(T)-2022

Local Port of Port Phillip

Williamstown

Williamstown Mooring Field – Isolated Danger Buoy Missing

Date: Immediate

Details: Mariners are advised that the isolated danger buoy lit with characteristics Fl(2)10s, in the eastern portion of the Williamstown Mooring Field at approximate location 37°51.413'S, 144°54.229'E (WGS84) is missing.

The buoy marks a submerged navigational hazard and will be re-instated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the missing buoy's location.

Charts & Publications

Affected: AUS 143, 154, 155

Further Notice: A further Notice will be issued

If you require further information please contact Parks Victoria on 13 1963.

Peter Kemp

A/Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.