

The following Notice to Mariners is published for general
information.

Victorian NTM 381 - Buoy 33 temporarily unlit

Effective 01st November 2022

Details: Buoy No 33 in position 38° 17.7774' S, 145° 13.8739' E is
temporarily unlit

Mariners are advised to proceed with extreme caution when in
the vicinity of this buoy.

Further Notice: A further notice will be issued



Capt. Shane Vedamuttu

Harbour Master

Port of Hastings