

The following Notice to Mariners is published for general information

**Australia – Victoria**  
**No. 426 (T) - 2022**  
**PORT OF MELBOURNE**  
**PORT PHILLIP BAY**  
**EAST CARDINAL MARK BUOY - REDEPLOYED**

**Date:** 5 December 2022

**Refers:** NtM 415 (T) – 2022 and is hereby cancelled

**Details:** Mariners are advised that an East Cardinal Mark Buoy has been redeployed to its original established position as follows:

| <i>Established Position</i> |                  | <i>Characteristics</i> |
|-----------------------------|------------------|------------------------|
| <i>Latitude</i>             | <i>Longitude</i> |                        |
| 38° 13.909' S               | 144° 50.614' E   | Q (3) 10s              |

For further information, please contact Melbourne VTS on VHF Channel 12 or 9644 9700.


**Charts & Publications affected** AUS 143

**Further notice:** No further notice will be issued.



**Warwick Laing**  
Harbour Master

## East Cardinal Mark Buoy - redeployed



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic).  
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website  
[www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)