

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia - Victoria

No. 457 (T) - 2022

PORT OF MELBOURNE STATION PIER INNER EAST SUBMERGED OBSTRUCTION

Date: 12 December 2022

Refers: N/A

Details: Mariners are advised of a submerged obstruction (fender) that exists in the

immediate vicinity of the wharf face at Inner East Station Pier.

A temporary yellow buoy has been established in position 37° 50.595' S, 144°

55.928' E to mark the position of the submerged obstruction.

For more information, please contact Melbourne VTS on (03) 9644 9700 or on

VHF Channel 12.

Mariners are advised to navigate with caution in the vicinity of the

submerged obstruction.


Charts & Publications affected

AUS 155, ENC AU5MEL01

Further notice: Further notice will be issued.

Warwick Laing Harbour Master

Inner East Station Pier – yellow buoy marking location of submerged obstruction



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.