

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 26 June 2023
Australia – Victoria

No. 266(T) – 2023

Local Port of Port Phillip

Rosebud
Wind Sports Zone Special Mark Buoy Missing

Date: **Immediate**

Details: Mariners are advised that the unlit Wind Sports Zone special mark buoy, from approximate charted location: 38°21.226'S, 144°53.332'E (WGS84) is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the missing buoy.

Charts & Publications

Affected: AUS 143

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.