

**Australia – Victoria**

**No. 365 (T) - 2023**

**PORT OF MELBOURNE  
PORT PHILLIP BAY**

**TEMPORARY WAVE MONITORING BUOYS**

**Date:** 8 September 2023

**Refers:** NtM 014 (T) – 2023 and is hereby cancelled.

**Details:** Mariners are advised the **Central** wave monitoring buoy (as identified in the below table) has been re-established in position **38° 03.811' S 144° 52.012' E**.

The following table of buoys established in the following positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or about November 2023.

<b><i>Approximate Location</i></b>	<b><i>Latitude</i></b>	<b><i>Longitude</i></b>	<b><i>Characteristics</i></b>
<b><u>Port Melbourne Waters</u></b>			
Werribee	37° 59.100' S	144° 46.512' E	FL (Y) 2.5s
Central	38° 03.811' S	144° 52.012' E	FL (Y) 2.5s
<b><u>Local Port of Port Phillip</u></b>			
Sandringham	37° 58.719' S	144° 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	FL (Y) 2.5s

For further information, contact Melbourne VTS on VHF Channel 12 or 9644 9700

**Mariners are advised to navigate with caution in the vicinity of the buoys.**

**Charts & Publications affected:**

AUS143, AUS155, AUS157

ENC AU5MEL01, AU5RIP01

**Further notice:** Further notice will be issued.



**David Tilsley**  
Deputy Harbour Master  
(Navigation Services)



**WAVE MONITORING BUOY**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)  
The requirements of section 232(2) have been taken into account.

---

Ports Victoria Notices to Mariners can be downloaded from the website, [www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)