

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Australia – Victoria

## No. 389 - 2023

## PORT OF MELBOURNE HARBOUR MASTER'S DIRECTIONS EDITION 13.1

Date:	29 September 2023
Refers:	NtM 296(T)–22, NtM 345(T)-22, NtM 472(T)-22, NtM 127(P)-23, NtM 149(T)-23, NtM 220(T)-23, NtM 382 (P)-23 and are hereby cancelled.
	OI 04-2022, OI 02-2022, OI 04-2020 and are hereby cancelled.
	Harbour Master's Directions – Melbourne Edition 13, September 2022 and is hereby withdrawn.
Details:	Mariners and port users are advised effective immediately, Harbour Master's Directions – Melbourne Edition 13, September 2022 is withdrawn and replaced by <b>Harbour Master's Directions – Melbourne Edition 13.1, September 2023</b> .
	Mariners are advised since promulgation of NtM 382(P)–23, additional corrections to Harbour Master's Directions – Melbourne Edition 13.1, September 2023 have been made. Please refer to the updated record of change document.
	Please refer to the extant Notice to Mariners in force providing consolidated tables of maintained depths for berth pockets, channel reaches, swing basins and least depths for anchorages.
	Harbour Master's Directions – Melbourne Edition 13.1, September 2023 and record of change is available on <u>www.vicports.vic.gov.au.</u>
Charts & Publications affected:	Harbour Master's Directions – Melbourne Edition 13.0, September 2022
Further notice:	No further notice will be issued.

Warwick Laing Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.