

The following Notice to Mariners is published for general information

**Australia – Victoria**

**No. 398 (T) - 2023**

**PORT OF MELBOURNE  
STATION PIER INNER EAST  
FENDER WORKS**

**Date:** 4 October 2023

**Refers:** N/A

**Details:** Mariners and port users are advised that fender works will be conducted at **Station Pier Inner East** between chainage **240m and 480m**.

Works including diving activities are expected to be conducted from **9 October to approximately 16 October 2023**.

Fender works will be supported by the following vessels:

- ***MV Ando***
- ***MV Oversea***
- ***MV Wizard***
- ***MV Nuwi***
- ***MV Franjo DSV***
- ***MV Lobo DSV***
- ***Rhumb Construction Barge***

Restrictions for passing vessels during works:

- ***Minimum wake and wash***
- ***Minimum passing distance of 50m***

Vessels engaged in diving works will display International Code flag “Alpha” during diving operations.

The works supervisor can be contacted on 0488 939 222 or 0438 846 568. ***MV Oversea*** can be contacted on 0420 924 172 and VHF channel 12.

**Mariners are advised to navigate with additional caution in the vicinity of Station Pier Inner East.**

For more information, contact Melbourne VTS on 9644 9700 or VHF channel 12.

**Charts &  
Publications  
affected:** AUS 155  
ENC AU5MEL01

**Further notice:** Further notice will be issued.


A handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke extending to the right.

**David Tilsley**  
**Deputy Harbour Master**  
**(Navigation Services)**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)  
The requirements of section 232(2) have been taken into account.

---

Ports Victoria Notices to Mariners can be downloaded from the website, [www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)



**NOT FOR NAVIGATION**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.