

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

## Australia – Victoria

## No. 411 (T) - 2023

## PORT OF MELBOURNE PORT MELBOURNE CHANNEL – SOUTH BEACON 8 PILE REMOVED

Date: 10 October 2023

Refers: NtM 346 (T) - 23 and is hereby cancelled. NtM 385 (T) - 23 and is hereby cancelled.

Details: Mariners are advised that the Port Melbourne Channel-South Beacon 8 pile, previously located in charted position 37° 53.856' S 144° 55.577' E, has been recovered.

A virtual aid to navigation **TB12** has been repositioned on the charted position of Port Melbourne Channel-South Beacon 8 until further notice.

A port hand lateral mark buoy is deployed as follows:

Buoy	Characteristics	Approximate Position
Port hand lateral mark	FI(2)R.4S	37° 53.829' S 144° 55.587' E
(without top mark)		

For further information, please contact Melbourne VTS on VHF Channel 12 or call 9644 9700.

Charts & Publications affected:


ENC AU5MEL01

Further notice: Further notice will be issued.


AUS 155

David Tilsley Deputy Harbour Master (Navigation Services)

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



**TEMPORARY BUOY** 

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.