

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia – Victoria No. 015 (T) - 2024

PORT OF MELBOURNE WEBB DOCK 2 EAST BERTH REMEDIATION WORKS

Date: 12 January 2024

Refers: N/A

Details: Mariners and port users are advised that bollard replacement and pile remediation

works, involving diving operations, will be conducted at **Webb Dock 2 East berth** from **15 January 2024** until approximately **August 2024** (reference attached

works plan and chartlet).

Diving operations and works will cease **30 minutes** prior to **arrival** and **departure** of coastal vessels from **Webb Dock 2 East berth**, including arrival/departure of the bunker vessel to a coastal vessel at the berth.

Diving operations and works may be conducted when a coastal vessel is berthed at Webb Dock 2 East **provided the vessel can be safely isolated**.

Diving operations and works at Webb Dock 2 East berth will continue during commercial vessel (SOLAS) movements to and from other berths in Webb Dock, with works operators monitoring wake and wash accordingly.

No diving operations or hot works will take place when **bunkering** is being conducted at Webb Dock 2 East berth.

Clear access for vessel, cargo, and mooring operations, both landside and waterside will be maintained during works.

The works may involve either of the following vessels:

- Lobo
- Eliza
- Matilda Mae
- Franjo

Restrictions for passing domestic commercial vessels during diving operations:

- Maximum speed of 6 knots
- Minimum passing distance of 50m

Dive vessels will display International Code flag Alpha during diving operations.

Works supervisor can be contacted on **0451 518 904** or **0499 939 159.** Vessels supporting works can be contacted on VHF channel 12.

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.

Mariners are advised to navigate with additional caution in the vicinity of Webb Dock 2 East berth during works.

For further information, please contact Melbourne VTS on 9644 9700 / VHF Channel 12 or email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected:

ENC AU5MEL01

Further notice: Further notice will be issued.

David Tilsley Deputy Harbour Master Navigation Services



NOT FOR NAVIGATIONAL USE



WORKS PLAN

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.