

The following Notice to Mariners is published for general information

Australia – Victoria

No. 199 (T) - 2024

PORT OF MELBOURNE

PORT PHILLIP BAY

SANDRINGHAM YACHT CLUB BUOY 5 TEMPORARILY REMOVED

Date: 8 May 2024

Refers: N/A

Details: Mariners are advised that **Sandringham Yacht Club Buoy 5 (SYC5), FI (4) Y 10s** established in approximate position **37° 58.81' S 144° 58.38' E**, has been **temporarily removed**.


For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected: AUS155
ENC AU5MEL01

Further notice: Further notice will be issued.



Warwick Laing
Harbour Master



NOT FOR NAVIGATIONAL USE

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Ports Victoria Notices to Mariners can be downloaded from the website, ports.vic.gov.au