

The following Notice to Mariners is published for general information

Australia – Victoria

No. 220 - 2024

PORT OF MELBOURNE PORT PHILLIP BAY SANDRINGHAM YACHT CLUB BUOY 6

Date: 22 May 2024

Refers: NtM 176 (T) – 24 and is hereby cancelled

Details: Mariners are advised that **Sandringham Yacht Club Buoy 6 (SYC6), FI (4) Y 10s**, has been re-established in position **37° 56.713' S 144° 57.080' E**.


For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected: AUS155
ENC AU5MEL01

Further notice: No further notice will be issued.



David Tilsley
Deputy Harbour Master
Navigation Services



NOT FOR NAVIGATIONAL USE



Sandringham Yacht Club Buoy 6

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
 The requirements of section 232(2) have been taken into account.