

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No. 209 OF 2018**

**PORT OF CORNER INLET AND PORT ALBERT**

**FRANKLIN RIVER CHANNEL**

**NAVIGATION AID REPLACEMENT WORKS**

**DATE:** 25<sup>th</sup> June 2018

**PREVIOUS NOTICE:** Notice to Mariners No 198(T) of 2018 is referred and cancelled.

**DETAILS:** Mariners are advised that the pile replacement program has been completed. A new position survey has been conducted and minor alteration to positions are recorded below.

1. Franklin River Channel No.4 unlit port hand lateral mark pile has been relocated to position;

Lat. 38° 43.417' S

Lon. 146° 19.559' E Datum WGS84

2. Franklin River Channel No.7 unlit starboard hand lateral mark pile has been relocated to position;

Lat. 38° 42.575' S

Lon. 146° 18.698' E Datum WGS84

3. Franklin River Channel No.13 starboard hand lateral mark beacon (Fl.G.6s) has been relocated to position.

Lat. 38° 42.420' S

Lon. 146° 17.680' S Datum WGS84

4. Franklin River Channel No.15 starboard hand lateral mark beacon (Fl.G.2s) has been relocated to position;

Lat. 38° 42.373' S

Lon. 146° 17.557' E Datum WGS84

5. Franklin River Channel No.17 starboard hand lateral mark beacon (LFl.G5s) has been relocated to position;

# NOTICE TO MARINERS

## GIPPSLAND PORTS



Lat. 38° 42.015' S  
Lon. 146° 17.323' E Datum WGS84

Further information can be obtained by contacting Gippsland Ports on 0351500500 or visit the Gippsland Ports website at [www.gippslandports.vic.gov.au](http://www.gippslandports.vic.gov.au)

**CHART** Chart Aus. 181  
**AFFECTED:**

**FURTHER** A further Notice shall be issued.  
**NOTICE:**

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**