

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA - VICTORIA

NO. 221 OF 2016

PORT OF ANDERSON INLET

ENTRANCE BAR & MAIN CHANNEL SHOALING

DATE: 22nd July 2016 – Effective Immediately

DETAILS: Mariners are advised that the Anderson Inlet Entrance Bar and the inner entrance Main Channel have continued to shoal causing channel location and depths to be unreliable.

Vessel movements across the Bar and in vicinity of the inner entrance Main Channel is dangerous and entails risk.

In addition, where the shoaling has developed inside the Entrance in vicinity of the Main Channel, the shoals attract swell that will at times break.

Mariners are advised to avoid navigating across the bar.

Further information can be obtained by contacting Gippsland Ports on 51 500500.

CHART Aus.801, NP14

AFFECTED:

FURTHER NOTICE: No further notice will be issued.

BEVIS HAYWARD

HARBOUR MASTER