

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA - VICTORIA

NO. 230 OF 2016

PORT OF ANDERSON INLET

**SPEED RESTRICTION ZONE BUOYS AND ISOLATED DANGER BUOY
REMOVED**

DATE: 09th August 2016 – Effective Immediately

PREVIOUS NOTICE: NTM 17 of 2013 , NTM 29 (T) of 2014 refer and are cancelled.

DETAILS: Mariners are advised that the three Special Mark navigation buoys that indicated the limits of the Speed Restriction Zone in vicinity of Point Smythe, NTM 29 (T) of 2014, have been removed.
Mariners are further advised that the Isolated Danger Buoy, FI (2) 6s 2m 2M that was in transit with the three Special Mark navigation buoys, NTM 17 of 2013, has also been removed.

The channels and waterway in vicinity of the “snags” near Point Smythe undergo constant change, vessel operators are reminded to navigate in this region with great caution being mindful of the potential for tree debris to enter the waterway following storm and current induced foreshore erosion processes.

Further information can be obtained by contacting Gippsland Ports on 51 500500.

CHART AFFECTED: Aus.801, NP14

FURTHER NOTICE: No further notice will be issued.

CAPT. BEVIS HAYWARD

HARBOUR MASTER