

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria No. 239 of 2016 (Temporary) BASS STRAIT – PORT ALBERT – SHOAL INLET ENTRANCE

Date: EFFECTIVE IMMEDIATELY

Details:

Mariners are advised that Notice to Mariners No. 215 (Temporary) of 2016 is referred and cancelled. Mariners are advised that a temporary light has been established to replace the destroyed Shoal Inlet entrance light (on the eastern side).

The position of the light is:
Lat. 38° 40'.29" South
Lon. 146° 50'.7" East
(Datum WGS84)

Light Characteristic's
Fl. W. 2s 9m 5M

A permanent light will be installed be as soon as possible.

Mariners are advised to navigate with caution in the vicinity of Shoal Inlet entrance.

AUS Charts and publications affected:

AUS 181
Admiralty Sailing Directions, Australia Pilot Volume 2
Admiralty List of Lights and Fog Signals Vol K (K2540)

Victorian Charts and publications affected:

Nil

Further notice:

A further Notice will be issued.

**Peter Corcoran
Director, Maritime Safety**

18 August 2016