

The following Notice to Mariners is published for general information

MELBOURNE, 20 September 2019

AUSTRALIA – VICTORIA

No. 229 (T) – 2019

PORT OF MELBOURNE

PORT PHILLIP

**WATER QUALITY MONITORING BUOY – RESTORED TO NORMAL**

**Date:** 20 September 2019

**Refers:** NTM 222 (T) – 2019 is cancelled.

**Details:** Mariners are advised that the water quality monitoring buoy marked by a yellow special buoy, fitted with a yellow light, flashing every 2.5 seconds (Fl.Y.2.5s) in position 38° 03.500'S, 144° 58.000'E, to the west north west of Paterson River in the vicinity of the 20 meter contour, has been restored to normal.

For further information contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Cancel this notice on receipt


**Charts &**

**Publications affected:** AUS 155

**Further notice:** No Further notice will be issued.



**Andrew Hays**  
Deputy Harbour Master



**NOT FOR NAVIGATIONAL USE**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website [www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)



**YELLOW MONITORING BUOY WITH SPECIAL MARKER**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)  
The requirements of section 232(2) have been taken into account.

---

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website  
[www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)