

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Melbourne, 17 February 2020

Australia – Victoria No. 064 (T) – 2020 PORT MELBOURNE

## INSPECTION AND STRENGTHENING WORKS FOR SERVICES PROTECTION BETWEEN YARRA RIVER BEACONS 33/34 AND 35/36

Date: 17 February 2020

Refers: NTM 061 (T)/2020 refers and is cancelled.

**Details:** Mariners are advised that inspection and strengthening works for the services

protection between Yarra River beacons 33/34 and 35/36 will take place from Monday 17 February until approximately 31 May 2020. The works will involve diving and service boats. The works will take place during the river closure for the

dredging works.

Works will be conducted from the following boats:

MV Venture, MV Jazz1, MV Pro diver 3 (Support Vessels)

• MV Pro Diver and MV Alice (Primary Dive Vessels)

Vessels operating within the vicinity of the works area shall reduce vessel speed so as to create no wash and pass the support vessel at a safe distance. The on water works supervisor in operational control of the works is contactable on 0437 532 347 or VHF Ch.12.

For more details please contact Melbourne VTS on (03) 9644 9700 or on VHF Channel 12.

Mariners are advised to navigate with additional caution and reduce speed so as to create no vessel wash when in the vicinity of the works at the

services protection.


Charts & Publications

affected: AUS 154

Further notice: Further Notice will be issued.

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.




Figure 3. Overview of work zone and general positioning of traffic management vessel – When working EAST of the channel during Closure



**Figure 4.** Overview of work zone and general positioning of traffic management vessel – When working WEST of the channel during Closure

Andrew Hays Deputy Harbour Master