

The following Notice to Mariners is published for general information

Melbourne, 28 February 2020

Australia – Victoria

No. 086 (T) – 2020

**PORT OF MELBOURNE
SOUTH CHANNEL – SHOALING**

Date: 28 February 2020

Refers: N/A

Details: Mariners are advised that shoaling exists in South Channel in the following locations;

Location	Position	Least Depth
Between Entrance Beacon/ Popes Eye Beacon and Beacons 01/02	38° 17.730'S 144° 41.550°E	14.80m
Between Beacons 01/02 and Beacons 03/04	38° 18.009'S 144° 43.192°E	15.39m
Beacons 01/02 to Beacons 03/04	38° 18.037'S 144° 43.179°E	15.26m
Beacons 01/02 to Beacons 03/04	38° 18.135'S 144° 43.741°E	15.39m

For more information, contact Melbourne VTS on 9644 9700.

Mariners are advised to navigate with caution South Channel.

**Charts &
Publications**

affected: AUS 158

Further notice: Further notice will be issued.



**Andrew Hays
Deputy Harbour Master**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au