

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia – Victoria No. 204 – 2020 PORT OF MELBOURNE

SOUTH WHARF 28 WITHDRAWN AND REVISED BERTH INFORMATION

Date: 08 July 2020

Refers: NTM 202 (T) / 2020

Details: Mariners are advised that due to changes to the berth pocket at South Wharf,

the dimensions of the berths have now been changed as per the table in the Harbour Masters Directions 11th Edition May 2019, Table 3(j) Berth

information, berthing and unberthing:

Table 3(j) Berth information, berthing and unberthing

Berth		Maintain ed depth (m)	Ship's limits at berth (m)		Wharf height (m)	General remarks
Name	Leng th (m)	Berth	Max. draug ht	Max. length	above Chart Datum	General remarks
South Wharf 27	<mark>215</mark>	10.4	<mark>9.80</mark>	<mark>186</mark>	3.5	Bulk cement and common user berth.
South Wharf 29	<mark>220</mark>	9.4	8.8	185	3.5	Layup and common user berth.

As a result of the changed berth pockets, the berth of South Wharf 28 has been withdrawn from service.

For more information contact Melbourne Vessel Traffic Services on VHF Channel 12 or 9644 9700.

Charts & Publications

affected: Harbour Masters Directions 11th Edition May 2019 Section 3.15 Table 3(j).

Further notice: No further notice will be issued.

Kell Dillon Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.