



## VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

Victorian NTM 273 - Western Port

Buoy No 5 unavailable until further notice

Effective                    28<sup>th</sup> September 2020

Details:                    Buoy No 5 has been removed from position 38° 28.41' S  
145° 08.32' E and will not be available until further notice

A further notice will be issued

A handwritten signature in blue ink, appearing to read 'Shane Vedamuttu', with a horizontal line underneath.

Capt. Shane Vedamuttu

Harbour Master

Port of Hastings