

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 21 December 2021
Australia – Victoria

No. 411 - 2021

Local Port of Port Phillip

Sorrento
Sorrento Pier Western Lower Landing Fenders Repaired

Date: **Immediate**

Previous Notice: 344(T)-20 is referred and cancelled

Details: Mariners are advised that the berthing fenders on the Sorrento Pier western low landing, at approximate location (WGS84) 38°20.132'S, 144°44.741'E have been repaired. Mariners should check weather, tides and condition of fenders above and below the waterline for suitability of berthing their vessel on any structure.

Mariners are advised to navigate with caution within the vicinity of Sorrento Pier

Charts & Publications

Affected: AUS 143, 150, 788

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.