

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 21 December 2021
Australia – Victoria

No. 416 - 2021

Local Port of Port Phillip

Portsea

Port Phillip Heads Marine National Park – Portsea Hole Special Mark Buoy Light Reinstated

Date: **Immediate**

Previous Notice: 377(T)-21 is referred and cancelled

Details: Mariners are advised that the special mark buoy, with characteristics Fl.Y.5s, marking the western boundary of Portsea Hole at approximate location (WGS84) 38°18.671'S, 144°42.555'E (WGS84) has been reinstated.

Mariners are advised to navigate with caution within the vicinity of the Portsea Hole.

Charts & Publications

Affected: AUS 144, 158

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.