

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

## Australia - Victoria

No. - 419 (T) - 2021

## PORT MELBOURNE PORT PHILLIP TEMPORARY WAVE MONITORING BUOY ESTABLISHED AT PORT MELBOURNE WATERS AND LOCAL PORT OF PORT PHILLIP-EXTENDED

Date: 22 December 2021

Refers: NtM 347 (T) / 2020 and is hereby cancelled.

**Details:** Mariners are advised that the buoys established in the following positions, within the

local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or

about November 2022.

Approximate Location	Latitude	Longitude	Characteristics
<u>Port Melbourne</u> <u>Waters</u>			
Werribee	37° 59.100´ S	144º 46.512´ E	FL (Y) 2.5s
Centre of Bay	38º 03.804´ S	144º 52.002´ E	FL (Y) 2.5s
<u>Local Port of Port</u> <u>Phillip</u>			
Sandringham	37° 58.719′ S	144° 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	FL (Y) 2.5s

For further information contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Mariners are advised to navigate with caution in the vicinity of the Buoys

Charts &

**Publications** AUS 143,150, 155 and 158

affected

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.

Further notice:

No further Notice will be issued

Kell Dillon Harbour Master



YELLOW MONITORING BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.