

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 02 February 2022 Australia – Victoria

No. 040 - 2022

Local Port of Port Phillip

Southern Port Phillip Pinnace Channel Aquaculture Fisheries Reserve Boundary Marker Lights Reinstated

Date: Immediate

Previous Notice: 014(T)-2022 is referred and cancelled

Details:

Mariners are advised that the lights on the following special mark buoys, marking the boundary of Pinnace Channel Aquaculture Fisheries Reserve have been reinstated.

Navigation Aid	Approximate Location (WGS84)	Flash sequence
Southernmost Boundary Marker Buoy	38°15.693'S, 144°49.581'E	FL(4) Y.12s
Westernmost Boundary Marker Buoy	38°14.257'S, 144°48.864'E	FL(4) Y.12s

Mariners are advised to navigate with caution within the vicinity of Pinnace Channel Aquaculture Fisheries Reserve.

Charts & Publications Affected: AUS 143, 157.

**Further Notice:** No further Notice will be issued.

If you require any further information please contact the Victorian Fisheries Authority on 0417 538 442.

Victor Teoh

Manager Regional Operations Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

