NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

Australia - Victoria No.067 of 2022

PORT OF GIPPSLAND LAKES

NORTH ARM - LAKES ENTRANCE STARBOARD LATERAL MARK BUOY ESTABLISHED

DATE: 17th February 2022

PREVIOUS NOTICE:

Notice to Mariners No.291(T) of 2019 is referred and cancelled.

DETAILS: Mariners are advised that the Temporary Starboard Lateral mark

buoy (FI.G.2s) in position;

Lat. 37° 53.012' S

Lon. 147º 58.059' E Datum WGS84

Is now established in the same position Permanently

CHARTS ENC AUSLEN01

AFFECTED:

PUBLICATIONS Gippsland Ports Waterways online website available at;

AFFECTED: https://www.gippslandports.vic.gov.au/boating/waterways-online/

FURTHER No further notice will be issued.

NOTICE:

CAPT. BEVIS HAYWARD HARBOUR MASTER