

Australia – Victoria

No. – 087 (T) - 2022

PORT MELBOURNE PORT MELBOURNE CHANNEL BEACON 1 MISSING

Date: 08 March 2022

Refers: N/a.

Details: Mariners are advised that Port Melbourne Channel Beacon 1 has broken, and the remaining pile is protruding 8 metres above the seabed in vicinity of 37° 55.6' S 144° 55.7' E. The location of the missing beacon has not yet been established.

Virtual AIS **ATON TB8** has been deployed in this position. A lit temporary buoy will be deployed when weather conditions permit.

Charts & Publications affected AUS 155

Further notice: Further Notice will be issued



**David Shennan
Harbour Master**



NOT FOR NAVIGATIONAL USE

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au