

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

## Australia – Victoria No. 088 (T) - 2022 PORT MELBOURNE PORT MELBOURNE CHANNEL BEACON 1 TEMPORARY BUOY IN PLACE

11 March 2022 Date: NtM 087 (T) / 2022 and is hereby cancelled. Refers: Details: Mariners are advised that Port Melbourne Channel Beacon 1 has broken, and the residual pile is protruding 8 metres above the seabed in vicinity of 37° 55.6' S 144° 55.7' E. A temporary starboard hand buoy with light characteristics FI(2)G 4s has been positioned 20m west from the pile toe. Virtual AIS ATON TB8 remains active in position of the hazard. For further information, please contact Melbourne Vessel Traffic Service on VHF Channel 12 or 9644 9700. Mariners are advised to navigate with caution in the vicinity of the Port Melbourne Channel Bcn 1. Charts & Publications AUS 155 affected

Further notice:


Further Notice will be issued

D. 1. Sheanan


David Shennan Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.





This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.