

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia – Victoria

No. 105 (T) - 2022

PORT MELBOURNE PORT MELBOURNE CHANNEL BEACON 1 RESIDUAL PILE PROTRUSION REMOVED


Date:	23 March 2022
Refers:	NtM 088 (T) / 2022 and is hereby cancelled.
Details:	Mariners are advised that Port Melbourne Channel Beacon 1 residual pile protrusion is now removed
	The temporary starboard hand buoy with light characteristics FI (2)G 4s and Virtual AIS ATON TB8 is still in place and active in position.37°55.6'S144° 55.7E'
	For further information, please contact Melbourne Vessel Traffic Service on VHF Channel 12 or 9644 9700.
	Mariners are advised to navigate with caution in the vicinity of the Port Melbourne Channel Bcn 1.
Charts & Publications affected	AUS 155
Further notice:	Further Notice will be issued

D.1. Sheanan


David Shennan Harbour Master

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.





This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.